

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION



LAND CORNER RECORD

T. 41 .. NR 28-29 .. W

D i c k i n s o n .. COUNTY

DESCRIPTION OF CORNER Section corner common to Section 18, 19, 13, 24

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 8" H, Maple (S 13 NBT) N 48°W 96 Links

6" H, Maple (S 18 NBT) N 84°E 62 Links

9" Basswood (S 24 NBT) S 43°W 56 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was re-established on N. - S. township Line by

proportionate measure. No evidence of original corner.

Corner lies 25 links east of wood s road.

Corner was placed and witnessed September 24, 1959 with Frank J. Bray.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 4/29/60  
REGISTERED LAND SURVEYOR  
Billy D. Buckler