MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T 41 NR 28-29 W

			- -	D_i_c_k_i	nson	COUN	I
DESCRIPTION	OF CO	ORNER Sect	ion_cormer c	ommon to Se	ctions 19. 3	30, 24, 25.	
DESCRIPTION	OF CO	RNER MONU	MENT1	Pipe with	4ª Brass Car	·	
WITNESSES	TO COP	INER _24" W.	Pine_Smag _	(s_19_NB	T) N_40°_	E 38 Links	3
		6* As	pen	_ (s_30 NE	¶)s 52°	E26 Link	5
		8" W.	Birch	_ (s 24 Ne	T) _ N 38°	W 38 Links	3

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced from two W. Pine B.T. s. Both stumps are badly burned and rotted. Distance north to stream checks good.

Corner was placed and witnessed September 21, 1959 with Frank J. Bray.

SURVEYORS SEAL

SIGNED Sully & Suckelis DATE 4/29/60
REGISTERED LAND SURVEYOR

Billy D. Buckler