

1. Public Land Survey, T 41N R 28W L-9  
 T \_\_\_\_\_ R \_\_\_\_\_  
 T \_\_\_\_\_ R \_\_\_\_\_  
 T \_\_\_\_\_ R \_\_\_\_\_  
 2. Property Controlling S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
 in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
 3. Miscellaneous S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
 Property in Sec. S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

**DICKINSON  
CO.**

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
 5. Private Claims \_\_\_\_\_

I, David Babbitt, in a field survey on 9/25, 19 85, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

L-9. South 1/4 cor. of Section 24. Set Mich. Cons. Dept. brass cap monument.  
 Billy D. Buckler witnesses (1955)  
 11" aspen N47°E 41 links.  
 9" aspen S59°W 36 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

L-9. Found Department of Natural Resources "brass" monument. Re-witnessed as found.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-9. Cons. Dept. brass monument. 9" R. Pine N86°W 24.7'  
 9" R. Pine N33°W 23.35'  
 12" Tamarack S61°E 102.3'  
 10" Aspen S82°E 130.0'

	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

Signed by

*David B. Babbitt*

Date

*2-11-86*

Surveyor's Michigan License No.

RLS 21558