		•								
		LAND CORNER	R RECORDATION CERTIF	ICATE		2는 점			IJ	
_		Filing Requirer	Filing Requirement of Act 74, Mich. P.A. 19			*### 55%			1.7	
For corner						(154) (35)		<u></u>	\bigcirc	
Dick	dinson	Located In:	Corner Code ##			- 1		<u></u>		
	(County)					- : <u>-</u> : - : - : : : : : : : : : : : : : : :			أحداً مبير ومعدده	
1. Public	Land Survey	T LIN R 29W T " R " T " R " T R R "	K-9 1-9 M-9	SURVE CORNE 345 O	Y PUG	R GRO Der≺Mo O AT∠A	UP AS	D SHIT IBUY N	COUNT PRICIA LIC AC IELD O	T.
2 Proper	ty Controlling S	T R				FP				
in Sect		T R		•			TY REP	RESEN	TATIVE	<u> </u>
3. Miscell		T R	-	Danist.	4 F		·	o =:-		
	·	T R		Registe	er of L	eeas :	tamp	& FIIE	Numbe	≱r
	.,									
4. Lot No	Record	ded Plat				A 5 1				
					AB	TI	E F	G H	I J K	<u> </u>
				2	<u></u>	\$	-4-	\$	<u> </u>	<u> </u>
				3					 	
				4	 	- 	<u> </u>	10	111	12-
1. Edward	<u>Kazianka</u> , in a	field survey on <u>Oct. 12</u>	, 19 <u>.93</u>	_ , 5	\sqcup					
			1970, the corner points mention		18	j	16-		14-	13-
			rules therefore as required in t ent of the interior, Bureau of La					ĹĽ	ĺ	L. Ľ.
		•	ooints mentioned in lines 3, 4 and				21-			
		· ·	and Surveyors or by a Decree o	fa' o	_ 13_	1—20— 			23-	
		iblished, monumented, re-mo	numented, recovered, found	as	1	1			1 9	
expressed b			•	10	00	29 I	28—	27	26	25 I
		s, all in the same town and	range, may be recorded	. 11		1	i 		 	
on	this certificate.		1	12	-3¦i	32	-33	34	35—	-36-
A				13	L	1		Щ	Щ	
		ment and accessories and/o	or subsequent restoration: s. W. Pine 12 S63V	/ h9 1k	.					
			iron pipe. 4-29-60	, 41 TW	rD •				-	
		W 3.96 chains. No								
			. Tamarack 16 S11V	7 60 lk	re					
	x o b o w b a.	TTT TO MOUNT	- Immediate To Mark	,						
]	Dept. of Conser		s. W. Pine 24 N35V iron pipe. 4-29-60 N38W 38 lks.		IS •					

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - K-9 Dept of Conservation Brass cap and iron pipe.

Pine snag 24 NAOE 38 1ks.

- L-9 No evidence of original corner or accessories found. Set Quarter Corner by proportionate measurement at mid-point and on line between section corners 2 mile to the east and west.
- M-9 Dept. of Conservation Brass cap & iron pipe.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - Dept. of Conservation corner.

W. Pine 28 Sh8W 3.96 Chains. Tamerack 2 N23W 39.L2 feet.
Tamarack 2 S65W 56.10 feet. " 6 S26E 139.77 feet.

L-9 2 inch Alum cap on a 5 foot # 6 re-rod set in north edge of flooded stream.
Cedar 22 N02W 41.95 feet. B. Ash 7 N65W 59.55 feet.
B. Ash 12 S0LW 65.93 feet. " 11 S3LE 73.15 feet.

M. O. Dert of Conservations

Dept. of Conservation corner. W. Birch 13 N38W 38 lks.

Aspen 8 N52E 13.15 feet.

Maple 11 S63W 30.35 feet. Aspen 10

Spruce 10 N12W 25.05 feet.

Surveyor's Michigan License No.

EDWARD