

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 41. NR 28 & 29. W

D i c k i n s o n COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 25 and 30

DESCRIPTION OF CORNER MONUMENT 1" Iron Pipe with 4" Brass Cap

WITNESSES TO CORNER 10" Cedar (1/4s NBT) N 55° W 73 Links

8" Cedar (1/4s NBT) S 5° E 28 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was re-established by setting it on line and midway between section corners. No evidence of original corners.

Corner was placed and witnessed June 3, 1960 with Frank J. Bray.

SURVEYORS SEAL

SIGNED

Billy D. Buckler  
REGISTERED LAND SURVEYOR  
Billy D. Buckler

DATE 9/13/60