

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 41. NR. 29. W

D i c k i n s o n COUNTY

DESCRIPTION OF CORNER 1/4 corner for section 32 on 4th correction line

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 9" J. Pine (1/4s NBT) N 49° E 60 Links

5" Aspen (NBT) N 14° W 25 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced from possible B.T. a W. Pine Stump bottom bearing N 54° W 35 Links. Position agrees with section corners, east and west.

Corner was placed and witnessed May 31, 1960 with Frank J. Bray.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR
Billy D. Buckler

DATE 9/13/60