Cons. 4047 REV. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. ___41___ N.R. __29 W ___

	<u>Dickinson</u>	COUNTY
DESCRIPTION OF CORNER	the corner for sections 32-33	
CORNER MONUMENT	1" pipe with 4" aluminum cap.	
DATE MONUMENT PLACED AND	9-26-61	
WITHESSES TO CORNER	9 soft maple (S NBT) S 820 57 links	
N	8" Cedar " " N 48°W 69 links	
33	Corner lies 3 3/4 chains south of road.	
CIRCLE COMER REGISTERED	AMD	

DESCRIPTION IN SETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established midway and on line between two section corners. No evidence of original corner.

SURVEYOR'S SEAL

SIEMED Silly D. Suckles DATE March 13, 1962
REGISTERED LAND SURVEYOR

Billy D. Buckler