

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 41 N.R. 28 & 29


Dickinson COUNTY

DESCRIPTION OF CORNER South 1/16 Corner for Secs. 9, T41N R29E, 12, & 7, T41N R28E

CORNER MONUMENT 1" Iron Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 7/7/64

WITNESSES TO CORNER..... 5" Cedar (S1/16 NE), N 59° E, 21 lbs.



CIRCLE CORNER REGISTERED

8" Cedar (S1/16 NE), S 40° E, 39 lbs.

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was placed midway and on line between 1/4 Corner to North and Section Corner to South. Old post 4 lbs. to NE.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 10/27/1964
REGISTERED LAND SURVEYOR