

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T 41-42 NR 22W

Dickinson COUNTY

DESCRIPTION OF CORNER Sec. cor. for secs: 1-2-35-36

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 2" Balsam (S1 NBT) S50° E 36 Lks.

6" Balsam (S35 NBT) N87° W 34 Lks.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced at old Cedar Post set by unknown surveyor. Found down, rotten Cedar bearing N79° E 37 Lks. No other evidence. Cor. has been accepted by local residents for several years. Cor. placed and wit. 5/11/59 with Frank Bray, Engr. Aide.

SURVEYORS SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler DATE 8/14/59
REGISTERED LAND SURVEYOR