MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T_41 NR_29 ... W

| | | | | - | Dickin | reor | COUNTY |
|-------------|----|--------|-------------|-------------|-------------------|------------------------|---------------|
| DESCRIPTION | O | CORNE | R _1/4_Cor1 | ber pet | reen Section | s_21_and_22 | |
| DESCRIPTION | OF | CORNER | MONUME | NT <u>1</u> | Pipe with | 4" Brass Car | 2 |
| WITNESSES | то | CORNER | 5" Maple | (| (1/4e EBT) | 8 46° W | 53 1/2 Links |
| | | | 10°_Tellar | Birch | (<u>1/44</u> BF) | _M_85 ₀ _M_ | _49_1/2_lipks |
| | | | | · - | _ | | |
| | | | | | | | |

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was placed midway and on line between Section corners.

This corner was placed and witnessed October 27, 1959 with Frank J. Bray.

SURVEYORS SEAL

SIGNED SILLY J. Suckler
REGISTERED LAND SURVEYOR

DATE 3/22/60