

✓

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 41. NR. 29. W

D i c k i n s o n COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 9, 10, 15, and 16

DESCRIPTION OF CORNER MONUMENT 1" Iron Pipe with 4" Brass Cap. . . . .

WITNESSES TO CORNER 11" Yellow Pine (S 9 NBT) N 12° W 3 Links . .

6" Yellow Pine (S 16 NBT) S 47° W 15 1/2 Links

12" Yellow Pine (S 10 NBT) N 60° E 35 Links . .

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR  
RESTORED. This corner was replaced <sup>at</sup> from old post set in pile of rocks.

Corner was placed and witnessed July 28, 1959.

SURVEYORS SEAL

SIGNED

*Billy D. Buckler*  
REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE 4/11/60