Cons. 4047

## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T.41 NR 29 W

						וֹס־נּ'ת	k_1_n_8	o_n_		- CO	UNI
DESCRIPTION	OF	CORNER	Zec1	t <u>io</u> n co	rner co	ommon to	o_Secti	ons_2_	3. 24.	_25,_2	<u>2</u> 6_
DESCRIPTION	OF	CORNER	MONU	MENT	" Pipe	with 4	<u> Brass</u>	Cap_			
WITNESSES	то с	CORNER .	20". W	Pine .	(S_2	26_NBT)_		5 <u> </u>	3•9	6_Chai	ins
							. <b></b> .		·		
							. <b></b> -		<del>-</del>		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced from two pine B.T.'s in good condition.

Corner lies in open marsh. Corner found by Forestry Division Survey Crew.

Corner was placed and witnessed October , 1959.

SURVEYORS SEAL

SIGNED Sully Suckles DATE 4/29/60
REGISTERED LAND SURVEYOR
Billy D. Buckler