

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 41. NR. 29. W

Dickinson COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 15 and 16

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 12" Elm (1/4s NBT) N 35° W 88 Links

8" Elm (1/4s NBT) N 72° W 83 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was re-established midway and on line between two Section Corners. No evidence of original corner. Corner lies in west side of open marsh.

Corner was placed and witnessed September 21, 1959 with Frank J. Bray.

SURVEYORS SEAL

SIGNED

*Billy D. Buckler*  
REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE 4/29/60