

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 41 NR. 29 W

D i c k i n s o n COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Section 11 and 12

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap.

WITNESSES TO CORNER 8" Aspen (1/4s NBT) S 42° W 14 Links

4" W. Spruce (1/4s NBT) N 75° E 22 Links

6" W. Spruce (1/4s NBT) N 46° W 12 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced from probable B.T. a W. Pine stump, bearing SE of corner. Stump burned badly. Position checks with Stream to north and several swamp edges.

Corner was placed and witnessed September 23, 1959 with Frank J. Bray.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR
Billy D. Buckler

DATE 4/29/60