

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 41 N.R. 29W


Dickinson COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 5-6-7-8

CORNER MONUMENT 1" Pipe with 3" Brass Cap in concrete

DATE MONUMENT PLACED AND WITNESSED 4-19-61 with H. S. Peterson, D. F.

WITNESSES TO CORNER..... 17" W. Pine (S8 NBT) S86°E 03½ links



17" W. Pine (S7 NBT) S89°W 92 links

1" Iron Pipe N29°W 26 links

AND 3/4" Iron Pipe S29°E 38½ links

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-witnessed as set by Hanna Mining Co. Found no original evidence of corner.

Note: Corner lies on top of E-W Rock ridge.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE January 30, 1962
REGISTERED LAND SURVEYOR
Billy D. Buckler