

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 41. NR. 29. W. 1
R. 41. S. 30. W.

----- Michigan ----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 18, 19, 21, 24

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap

WITNESSES TO CORNER -----

12" Spruce - S 27 W - 47 Links

16" Cedar - S 11 E - 72 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while making a partial resurvey of this area. Corner had been previously located by unknown Surveyor. Stream crossings in three directions, as per Gov't. notes, check o.k..

Corner was placed and witnessed October 28, 1953.

SURVEYORS SEAL

SIGNED

John C. [Signature]
REGISTERED LAND SURVEYOR

DATE

1/25/54