JAN 16 E.

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T 41 NR 29 W

•		Didentification.
DESCRIPTION	OF CORNER	1/4 Corner between Sections 28 - 33
DESCRIPTION	OF CORNER	MONUMENT_1" Pipe with " Brass cap
WIT TNESSES	TO CORNER	8" Cedar N. 37 E 19 Links.
		9# White Spruce S 15°W 18 Links.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

1/4 Corner set midway and on line between two Section Corners.

There is an old Cedar (down) believed to be marked by Timber Cruisers about 40 Links Borth of Corner. No evidence of Witnesse trees.

orner placedand witnessed Sept. 12,1955.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 1/12/56
REGISTERED LAND SURVEYOR