

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 41N R.R. 30W


Dickinson COUNTY

DESCRIPTION OF CORNER 1/4 corner for sections 9-10

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 7-17-62

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

5" B. Spruce (1/4 S NBT) S23°E 18 1/2 links

5" B. Spruce (1/4 S NBT) S86°W 16 links

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced at 3" - iron pipe was set by unknown surveyor. Found no evidence of original witnesses.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE February 28, 1963
REGISTERED LAND SURVEYOR
Billy D. Buckler