Cons. 4047 Rev. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 41N N.R. 30W

	Dickinson	COUNTY
DESCRIPTION OF CORNER _	Section corner common to Sections 13-14-23-24	
CORNER MONUMENT	l" pipe with 4" brass cap.	
DATE MONUMENT PLACED AN	- 1 11-	
WITHESSES TO CORNER	now new /climph N129W A5 links	
N !	22" W. Pine (S13NBT) N40°E 81 links	
24		
+		
	AMD	
CIRCLE CORNER RESISTERE	0	

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced at wood post set by unknown surveyor. Distance checks to features in several directions.

SURVEYOR'S SEAL

Silly D. Suchles

BATE January 23, 1963

REGISTERED LAND SURVEYOR

Billy D. Buckler