

✓

**MICHIGAN**  
**DEPARTMENT OF CONSERVATION**  
**FORESTRY DIVISION**

**LAND CORNER RECORD**

T. 4 NR. 20 W.

----- Madison ----- COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 11, 12, 13, 14

DESCRIPTION OF CORNER MONUMENT 2" iron with 4" iron cap

WITNESSES TO CORNER -----

No witness were available

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established, by double perpendicular measurement, by Forestry Division survey crew, while making a partial recovery of this area. Rock ledges in immediate vicinity, as per Gov't. field notes, check good. Remains of two probable I.T.'s still in place, badly rotted.

Corner was placed and witnessed October 28, 1955.

SURVEYORS SEAL

SIGNED John C. DeMott  
REGISTERED LAND SURVEYOR

DATE 1/28/56