

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 41 .. NR 30 W. . .

Dickinson

..... COUNTY

DESCRIPTION OF CORNER .. ~~Section~~ Corner common to ~~Sections~~ 25, 26, 35, 36

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap.

WITNESSES TO CORNER 10" Hemlock S 32° W 72 Links.

8" Yellow Birch N 60° W 53 Links.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

2" Iron Pipe set by unknown Surveyor, Fence line running East and North.
Y. Birch (down) badly rotted in proper position. (possible description
blaze on this Birch.

Corner found by Forestry Division Survey Crew.

Corner placed and witnessed July 27, 1955.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 1/12/56.
REGISTERED LAND SURVEYOR