## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. 41 N.R. 30 W

	Dickinson	COUNTY
DESCRIPTION OF CORNER S 1/16 Corner for S	Sections 8-9	
CORNER MONUMENT 1" Iron Pipe with 4"	Aluminum Cap	
DATE MONUMENT PLACED AND WITHESSED	63	
WITHESSES TO CORNER6" Elm (S 1/16 B)	r), S 61° E, 01½ Iks.	<del></del>
5 Cedar (S 1/16	BT), S 47° W, 15½ Iks.	····
CIRCLE CORNER REGISTERED		

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was placed midway and on line between 1/4 Corner to North and Section Corner to South.

SURVEYOR'S SEAL

Silly D. Buckler.

Billy D. Buckler

REGISTERED LAND SURVEYOR

DATE April 30, 1964