

# LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--	(DICKINSON COUNTY) LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. <u>41</u> N. R. <u>30</u> W.	#L-13
2. PROPERTY CONTROLLING IN SECTION	T. _____ N. S. R. _____ E. W.	_____
3. MISCELLANEOUS PROPERTY IN SECTION	T. _____ N. S. R. _____ E. W.	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Arthur O. Enger, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on August 21, 1979, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

**Corner L-13 (1/4 cor. on S side of Sec. 36, T41N, R30W on 4th Corr. Line):**  
 Found a 1" I.D. x 48" iron pipe with 4" brass cap as set by B. D. Buckler, L. S. #8887 on 7-27-55 and witnessed by him with a Red Oak 7 N86°W 75 lks. and an Aspen 6 N55°E 45 lks. Buckler's corner record is on file.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

**Corner L-13:** Marked an additional witness tree to replace Buckler's aspen, now dead.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

**Corner L-13:** Monument as set by Buckler  
 Red Oak 11 N84-1/2°W (mag.) 49.7 ft. "1/4S, NBT" (Buckler's)  
 Red Maple 7 S20° E (mag.) 17.4 ft. "1/4S, NBT" (Enger)  
 Declination 3° 35' West.

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

APPROVED AND SIGNED BY Arthur O. Enger DATE March 4, 1980

CHIEF OF SURVEY PARTY  
 \_\_\_\_\_  
 MICHIGAN REGISTERED LAND SURVEYOR  
 Arthur O. Enger

Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

