MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_42_ NR_27_W_

| | | | Dightingos COUNTY |
|-------------|----|--------|-------------------------------------|
| DESCRIPTION | OF | CORNER | 1/A Corner between Sections 19 & 30 |
| DESCRIPTION | OF | CORNER | MONUMENT_1"_Pipe_with_4" Brass_cap |
| WITTNESSES | то | CORNER | _ 5 Coder - N 15 W - 15 Links |
| | | | 97 Cedar + H 27 F - 10 Links |
| | | | 10" Coder = \$ 26 E = 15 Links |
| | | | |

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was pointed out to me by H. S. Peterson, District Forester, of Iron Mountain. One original B.T. still in place, in fair condition.

Corner was placed and witnessed January 31, 1952.

SURVEYORS SEAL

SIGNED SLAW DATE 2/6/52 PREGISTERED LAND SURVEYOR