

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 42N N.R. 28W


Dickinson COUNTY

DESCRIPTION OF CORNER 1/4 cor. for Secs. 22-27

CORNER MONUMENT 1" iron pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 11/9/66

WITNESSES TO CORNER..... 6" Cedar (1/2S)(NBT) N35°E, 06 lks.



7" Cedar (1/2S)(NBT) N57°W, 15 lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from old wood post and points of two older post found in ground. Cor. checks well with sec. cors. to east and to west.

SURVEYOR'S SEAL

SIGNED F. J. Bray DATE 1/16/67  
REGISTERED LAND SURVEYOR