Cons. 4047 REV. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. __ 42N ___ N.R. 27&28W

		YTRUO
DESCRIPTION OF CORNER	N1/8 between sections 25, T42N, R28W and 30, T42N, R27W	
CORNER MONUMENT	3/8" reinforcing rod and wood post	
DATE MONUMENT PLACED AND	WITNESSED 9/26/62	
WITHESSES TO CORNER	. 8* Cedar (BT) S20°W, 05 links	
2 5	8" Cedar (BT) N38°E, O8 links	
CIRCLE CORNER REGISTERED	AND	

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between 1/4 corner to south and section corner to north. Found old post down about 20 feet northeast.

SURVEYOR'S SEAL

Signed Silly & Sucheles

RESISTERED LAND SURVEYOR
Billy D. Buckler

Billy D. Buckler