

✓

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 42. NR. 28. W.  
T. 43. NR. 28. W.

----- Dickinson ----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 1, 2, 35, 36 -----

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap -----

WITNESSES TO CORNER 5" Spruce - S 43 E - 16 Links -----

6" Spruce - N 72 W - 37 Links -----

-----

-----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while making a partial resurvey of this area. Three original B.T.'s in place, badly rotted. Corner had been previously perpetuated by unknown persons.

Corner was placed and witnessed August 27, 1952.

SURVEYORS SEAL

SIGNED

*Leah C. DeLoe*  
REGISTERED LAND SURVEYOR

DATE 11/12/52