

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42 N.R. 28 W


Dickinson COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 22, 23, 26, 27

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 5/3/61

WITNESSES TO CORNER... 9" Cedar (S 23 NBT) N 62° E 32 Links



7" Cedar (S 27 NBT) S 27° W 18 1/2 Links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from two old wood posts and decayed Tamarack Stump on proper bearing and distance. No Marks visible. Corner seems to check with corners in vicinity.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE August 2, 1961

Billy D. Buckler