

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42 N.R. 27-28 W


Dickinson COUNTY

DESCRIPTION OF CORNER 1/4 Corner for Sections 13-18

CORNER MONUMENT 1" Iron Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 10/30/64 with R. Hinds

WITNESSES TO CORNER..... 5" Elm (1/4S NBT), S 29° W, 25 lks.



6" Elm (1/4S NBT), N 57° E, 21 lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced from down Cedar which has blazes and could be B.T.
(6" Cedar, West, 15 lks.)

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE December 8, 1964
REGISTERED LAND SURVEYOR