

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42 N. R. 28


Dickinson COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Secs. 16-21

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 4/9/64 with Wm. Alatalo

WITNESSES TO CORNER..... 8" Cedar ($\frac{1}{2}$ S NBT), N25°E, 24 $\frac{1}{2}$ Lks.



CIRCLE CORNER REGISTERED

8" Cedar ($\frac{1}{2}$ S NBT), N38°W, 58 $\frac{1}{2}$ Lks.

8" Cedar ($\frac{1}{2}$ S NBT), S26°W, 57 Lks.

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced from one Tamarack B.P. down but in excellent condition bearing: N 47°W, 20 links. Found bottom of wood post in place.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler DATE 8/24/1964
REGISTERED LAND SURVEYOR