

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42N N.R. 28W


Dickinson COUNTY

DESCRIPTION OF CORNER Sec. cor. for secs. 10,11,14,15

CORNER MONUMENT 1" iron pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 8/19/66

WITNESSES TO CORNER..... 7" Dead Cedar (S15)(NBT) S70°W, 19½ lks.



5" Dead Cedar (S11)(NBT) N30°E, 21½ lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set at old rotted off wood post and point of older post found in ground beside first post.

Rotted cedar stump bottoms check well for bearings and distances.

SURVEYOR'S SEAL

SIGNED F. J. Bray DATE 2/6/67
REGISTERED LAND SURVEYOR