## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

						Dicki	nson	COUNTY
					T	42-4	.3N	28W
DESCRIPTION OF CORNER <u>1/</u>	4 corner bet	twee	n Secti	Lons 6 a	ınd	31		
CORNER MONUMENT	. x 36" iro	n pi	pe with	ı 4" alv	min	um cap	) 	
DATE MONUMENT PLACED AND W	ITNESSED	Ju	ly 14,	1970				
VITNESSES TO CORNER	Hemlock	14	S38 <sup>O</sup> W	(mag.)	14.	5 ft.	"1/4S,	NBT"
N	Hemlock	10	West	(mag.)	8.	6 ft.	"1/4S <b>,</b>	NBT"
6	Sugar Mapl	e 6	N6°E	(mag.)	3.	6 ft.	"1/4S,	NBT"
	AND							
CIRCLE CORNER REGISTERED	)			<del> </del>		<del></del>		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

No subsequent monuments found, except for a 15" hemlock with old blazes on 4 sides 19.2 ft. west.

Corner re-established proportionately on line between section corner 2648.9 ft. east and section corner 2621.1 ft. west.

SURVEYOR'S SEAL

DISTRIBUTION: SIGN

SIGNED Withus C. Coggar REGISTERED LAND SURVEYOR DATE December 20, 1971

Arthur O. Enger

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68