STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

		Dickinson		COUNTY	
	T	42 N	R _	28 W	
DESCRIPTION OF CORNER North 1/16 corner between Section	ons	7 and 8			
CORNER MONUMENT 1" I.D. x 36" iron pipe with aluminum	n c	ap			
DATE MONUMENT PLACED AND WITNESSED July 13, 1970					
WITNESSES TO CORNER Cedar 12 S63°W (mag.) 23.8 f	ſt.	"1/16S, BT	11		
Cedar 7 N40°W (mag.) 24.3 f	ſt.	"1/16S, BT	11		
AND					
CIRCLE CORNER REGISTERED			-		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Not established in original survey.

No evidence that the corner had been established previously.

Corner established on line between section corner 1311.4 ft. north and 1/4 corner 1311.4 ft. south.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGN

SIGNED

REGISTERED LAND SURVEYOR Arthur O. Enger

DATE December 21, 1971

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047

Rev. 10/68