

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION



LAND CORNER RECORD

T. 42N N.R. 28W


Dickinson COUNTY

DESCRIPTION OF CORNER S 1/16 cor. for secs. 22-23

CORNER MONUMENT 1" iron pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 8/24/66

WITNESSES TO CORNER..... 9" Cedar (S 1/16) (BT) S48°E, 33 lks.



8" H. Maple (S 1/16) (BT) N31°W, 07 lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line bet. $\frac{1}{4}$ cor. to north and sec. corner to south.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 1/11/67
REGISTERED LAND SURVEYOR