

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42N N.R. 28W


Dickinson COUNTY

DESCRIPTION OF CORNER Sec. cor. for secs. 9-10-15-16

CORNER MONUMENT 1" iron pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 10/24/66

WITNESSES TO CORNER..... 11" W. Pine (S16)(NBT) S53°W, 44½ lks.



21" W. Pine (S9)(NBT) N05°W, 74 lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from two rotted w. pine stump bottoms which are in proper distance and bearing. Corner checks well with other cors. in area.

SURVEYOR'S SEAL

SIGNED F. J. Bray DATE 1/16/67
REGISTERED LAND SURVEYOR