

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42N N.R. 28W


Dickinson COUNTY

DESCRIPTION OF CORNER S 1/16 cor. for secs. 16-17

CORNER MONUMENT 1" iron pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 10/31/66

WITNESSES TO CORNER..... 14" Cedar (S 1/16)(BT) S31°W, 17½ lks.



12" Cedar (S 1/16)(BT) N20°E, 26 lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line bet. $\frac{1}{4}$ cor. to north and section cor. to south.

SURVEYOR'S SEAL

SIGNED F. J. Bray DATE 1/16/67
F. J. Bray
REGISTERED LAND SURVEYOR