LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in				
Dickinson (County)	Located In:	Corner Code ≠≠		
1. Public Land Survey	T 42N R 28W T R R T R R	H-2,H-3,I-2.		
	T R			
	T R			
-	<u>†</u> <u>R</u>		Register of C	Deeds Stamp & File Number
Property in Sec. S	T R			
4. Lot No, Records	d Dist			
5. Private Claims, Records			A B	CDEFGHIJKLM
5. Frivate Claims				┼╌╏╌┼╴╽╌╂╴╏╶┼╴╏
			3	}-}-}-
			4 <u> </u>	10 11 12
, David B. Babbitt , in a fi	eld survey on6/28	, 19	_ , 5	
do hereby certify that under requiremen	nts of P.A. 74, Michigan P.A.	of 1970, the corner points mention		17-16-15-14-13-
in lines 1 and 2 above were in conformations of survey instructions of				
Management or by a decree of a Court of	f Law and/or that the corns	r points mentioned in lines 3, 4 an	id 5 8 19	20 -21 -22 -23 -24
above were in conformance with the ru				
Court of Law; established, re-estable expressed below:	ished, monumented, re-r	nonumentea, recoverea, touna	as 10	1 29 1 28 1 27 1 26 1 25 1
NOTE: Not more than 4 corners,	all in the same town or	id range, may be recorded	11	
on this certificate.	dii iii file saile tomii ei	id lange, may be recorded	12 _ 31_	
			13 🗓	
A. Description of original monum	ent and accessories and	d/or subsequent restoration:	-	
B. Description of corner evidence H-2. Set at the interse H-3. Set MPOL between t falls in front of I-2. Found 1½" pipe not prop. to GLO and i	found and/or method a ection of the N-S he SE and SW sec very old cedar s of record. Cou s about 18' East	and E-W 1/4 lines of tion corners of Secti ign up tree and in li ld not locate OBT's. of a straight line:	olishing corner: f Section 3. ion 3. No s ine of very Found pipe from section	
C. Description of monument for continuous through the description of monument. 13" maple, S44W, 25.9' 10" maple, S81W, 52.0' 12" maple, N63W, 47.3' 9" twin maple, N4W, 83.1	H-3. DNR 1 6" cedar, 1 6" cedar, 1 7" cedar, 1	Monument I-2. N46E, 14.6' 7" ma S14E, 12.85' 3" in S61W, 23.8' 9" ma		nt in 1½" pipe. 55.5' E, 25.3' 20.3'
	, D 11 2		11 -2	0.0
Signed by Favil	D- Babb	Date	11-28-	87
Surveyor's Michigan License No	21558		CARM ADDROGUES BY MUTUAL	AN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

FORM APPROVED BY MICHMAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1883

Ob.