LAND CORNER RECORDATION CERTIFICATE Filing Regulrement of Act 74, Mich. P.A. 1970

For corners in Dickinson	Located In:										
(County)											
1. Public Land Survey	T R						-				
2. Property Controlling	S T R										
in Section 3. Miscellaneous Property in Sec.			Registe	r of I	Deed	s Sta	mp &	File	Num	ber	
4. Lot No, Re 5. Private Claims	corded Plat		2	A •	٦	D @	, •	H		<u>« :</u>	N
do hereby certify that under require lines 1 and 2 above were in- current manual of survey instruct Management or by a decree of a above were in conformance with Court of Law; established, re expressed below:	in a field survey on	370, the corner points mention les therefore as required in to st of the Interior, Bureau of La ints mentioned in tines 3,4 am nd Surveyors or by a Decree o umented, recovered, found	ied 6 ihe ind 7 d5 8	-1818	20		16	-15	23-26-35-		

- (E5) Section corner common to sections 8-9-16-17. Corner previously recorded by Frank J. Bray RLS in 1967 as monumented by a 1° iron-pipe with 4° aluminum cap and the following MBTs: 7° H. Maple (SB) (MBT) M75M 30 links, 8° M. Maple (SB) (MBT) M82E 45.5 links, Found no subsequent record.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (E5) Recovered monument as described at record bearing and distance from the N. Maple N75W NBI. The N. Maple in the NE quadrant has been cut. Remitnessed the monument as found, marking two new MBTs, described below.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. (ES) Fd. 1" pipe with 4" aluminum MONR Blazed and scribed the following new bearing trees: 8" sugar M69E 38.0" "\$9 N8T" 8" sugar \$56E 47.2" - "\$16 HBT" A fence car, post is west of the corner, 0.5'.

Surveyor's Michigan License No.