

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42 NR 29

Dickinson COUNTY

DESCRIPTION OF CORNER 1/4 corner between sections 21 and 28

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER Cedar 14" N 26 W 11 links

No other new bearing trees available.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced in roots of 10" hemlock that had been scribed for original corner. Tree still standing. Scribes very plain.

Corner was found while cruising timber in this area.

Corner was placed and witnessed on 15 August 1956

SURVEYORS SEAL


Henry S. Peterson

SIGNED _____
REGISTERED LAND SURVEYOR

8/16/56
DATE _____