LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson	Located In:	Corner Code #	
(County) West Branch Township 1. Public Land Survey	TR		
Property Controlling in Section Miscellaneous	T R S 25 T 43N R 27W S 25 T 43N R 27W S T R S T R	10	
Property in Sec. 4. Lot No. , Re	corded Plat		Register of Deeds Stamp & File Number
5. Private Claims			·
	8/21/2012	2AD	
i, Jeremy J. Pipp , i	n a field survey on 8/21/2012 74, Michigan P.A. of 1970, the corner po		2 - 7 - 8 - 9 - 10 - 11 - 12
above were in conformance with regulations and rules therefore as required in the current manual of survey 5			
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6 18 17 16 13 14 13 a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7			
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, g			
NOTE: Not more than 2 core on this certificate.	ners, all in the same town and range,	may be recorded	10 30 29 28 27 26 25 11 12 31 32 33 34 35 36

- A. Description of original monument and accessories and/or subsequent restoration:
- (10) South One-Sixteenth corner common to Sections 25 and 26. Not set in original survey, no evidence of subsequent establishment.
- (11) Southwest One-Sixteenth corner of Section 25. Not set in original survey, no evidence of subsequent establishment.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (10) Corner position established mid-point and on-line between the West One-Quarter corner and the Southwest corner of Section 25.
- (11) Corner position established at the intersection of the South and West One-Sixteenth lines of Section 25.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(10) DNR monument	(11) DNR monument
4" Tamarack N59E 37.30' (1/16S,BT)	6" Spruce N40E 92.62' (1/16S,BT)
5" Cherry S60E 43.33' (1/16S,BT)	14" Spruce S37E 121.34' (1/16S,BT)
4" Spruce \$67W 44.55' (1/16S,BT)	19" Spruce S56W 87.89' (1/16S,BT)
22" Tw. Maple N23W 31.97' (1/16S,BT)	5" Spruce N25W 124.04' (1/16S,BT)
All trees are blazed, scribed, and	All trees are blazed, scribed, and
painted. Measurements are to nail in	painted Measurements are to nail in
side of tree, bearings are magnetic.	bearings are magnetic.
	G.

August 29, 2012

Surveyor's Michigan License No.

For the Michigan Department of Natural Re

N STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 Revised May 14, 1975

Revised Jan., 1983 Rervised Oct., 1995