

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Dickinson</u> <small>(County)</small>	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S <u>33</u> T <u>43N</u> R <u>27W</u>	<u>14, 3, 5</u>
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

I, David Babbitt, in a field survey on March 13, 1986, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2							
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

- A. Description of original monument and accessories and/or subsequent restoration:
- 14 South 1/16 corner on the East Section Line-Section 33 not previously established
  - 3 North 1/16 on the West Section Line Section 33 not previously established
  - 5 North 1/16 Corner of Section 33 not previously established

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- 14 Set M.P.O.L. between the East 1/4 corner and the S.E. section corner of section 33
  - 3 Set M.P.O.L. between the West 1/4 corner and the N.W. section corner of section 33
  - 5 Set M.P.O.L. between the North 1/4 corner and the center of section 33 by closed traverse

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- |                              |                         |
|------------------------------|-------------------------|
| 14 (DNR Monument)            | 5 (DNR Monument)        |
| 3" Black Spruce S11W 4.85'   | 6" Black Ash S85E 70.6' |
| 10" Black Spruce S75E 23.15' | 6" Cedar S16E 99.62'    |
| 9" Black Spruce N27W 25.8'   | 12" Spruce S3W 117.45'  |
| 10" Black Spruce N60E 35.5'  | 7" Black Ash S8W 52.00' |
| 3 6" Cedar S60W 65.5'        |                         |
| 7" Cedar S39E 28.7'          |                         |
| 11" Cedar South 13.9'        |                         |
| 6" Black Ash N10W 110'       |                         |
| (DNR Monument)               |                         |

Signed by David B. Babbitt Date 6-9-86

Surveyor's Michigan License No. \_\_\_\_\_