LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For	corners	in

3. Miscellaneous

Property in Sec.

Dickinson (County)	Located In:	Corner Code ##	
. Public Land Survey	T A		
	T R		
	T R		
	T R		
Property Controlling	s <u>34</u> t <u>43N</u> R 27W		
in Section	S 34 T 43N R 27W	16.~	

Register of Deeds Stamp & File Number

_ , Recorded Plat _ 5. Private Claims

I,David Babbitt , in a field survey on	5/27/86	, 19 86
do hereby certify that under requirements of P.A. 74, Michi	gan P.A. of 1970, the c	orner points mentioned
in lines 1 and 2 above were in conformance with regula	tions and rules there	fore as required in the
current manual of survey instructions of the United State		
Management or by a decree of a Court of Law and/or that the		
above were in conformance with the rules of the Michigan		
Court of Law; established, re-established, monument	ed, re-monumented.	recovered found as
expressed below		

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- 15. West 1/16 corner on the S section line of Section 34. Not previously est.
- 16. East 1/16 cor. on the south section line of Section 34. Not previously est.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- 15. Set MPOL between the south 1/4 corner and the SW section corner of Section 34.
- · 16. Set MPOL between the SE section corner and the S 1/4 corner of Section 34.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- 15. DNR Monument.

DNR Monument.

Date

- 8" bl. cherry \$60E 4.8' 5" N30E 10.2' 6" bl. maple N30W 12.3'
- 7" h. maple 23.85' N54W 411 -
- 17.8 N36E Ğυ

18.5' S65E

5" aspen - \$85W - 14.6'

31.2' S33W