

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 43 N.R. 27 W


Dickinson COUNTY

DESCRIPTION OF CORNER Section Corner for Sections 9/10  
16/15

CORNER MONUMENT 1" Iron Pipe with 1/2" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 10-29-63

WITNESSES TO CORNER..... 11" Elm (S.9) (NBT) N 33° W 23 links



10" Elm (S.10) (NBT) N 51° E 23 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from old wood post (rotted & down) Corner checks good with corners in vicinity.

No original evidence.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 4-3-64  
REGISTERED LAND SURVEYOR  
Billy D. Buckler