

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43. NR. 27. W.

----- Dickinson ----- COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 29 & 30 -----

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap -----

WITNESSES TO CORNER 8" Cedar - N 38 W - 25 Links -----

8" Cedar - N 60 E - 38 Links -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was pointed out to me by H. S. Peterson, District Forester, of Iron Mountain. Corner had been perpetuated by unknown Surveyor, and was verified by Wm Johnson, County Engineer, of Iron Mountain. One original B.T. still in place, in very poor condition.

Corner was placed and witnessed January 29, 1952.

SURVEYORS SEAL

SIGNED Leaw C. Johnson DATE 2/5/52
REGISTERED LAND SURVEYOR