

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 NR 27 W

Dickinson

..... COUNTY

DESCRIPTION OF CORNER 1/4 corner between sections 23 and 24.

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER Cedar 13" N 10 W 25 1/2 links

Cedar 9" S 26 E 22 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from original cedar bearing tree in good condition.

Corner was found while cruising timber in this area.

Corner was placed and witnessed on 1 February 1956

SURVEYORS SEAL

Henry S. Peterson

Henry S. Peterson

SIGNED _____ DATE 2/8/56
REGISTERED LAND SURVEYOR