

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T⁴³ NR 27 W

Dickinson

COUNTY

DESCRIPTION OF CORNER 1/4 corner between sections 22 and 27

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER Hard maple 26" N 22 E 129 links

No other new bearing trees available.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from two original hemlock bearing trees in poor condition. Found scribe marks on piece of wood in remains of one stump.

Corner was found while cruising timber in this area.

Corner had been previously perpetuated by unknown surveyor.

Corner was placed and witnessed on 18 May 1956.

SURVEYORS SEAL

Henry S. Peterson
SIGNED Henry S. Peterson
REGISTERED LAND SURVEYOR

DATE 5/25/56