

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 NR. 27 W.

Dickinson

----- COUNTY

DESCRIPTION OF CORNER Section corner common to sections 1,2,11 and 12
DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap
WITNESSES TO CORNER Cedar stump 22" S 36 W 31 links, marked S 11 NBT
White spruce 6" N 13 E 40 links, marked S 1 NBT

Distances measured from center of brass cap to NBT notch.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced in remains of 16 inch cedar that had been marked for original corner. Stump of original bearing tree (cedar) in place with BT face plain on overgrowth. No other identifying marks. Have good corners 1 mile South and 1 mile west.

Corner was found while cruising timber in this area.

Corner placed and witnessed on 9 July 1957 with Norman J, Karsten.

SURVEYORS SEAL

Henry S. Peterson
SIGNED Henry S. Peterson DATE 7/11/57
REGISTERED LAND SURVEYOR