

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 27 W


Dickinson COUNTY

DESCRIPTION OF CORNER Section Corner for sections 17, 16

CORNER MONUMENT 1" Iron pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 11-1-63

WITNESSES TO CORNER..... 6" Tamarack (S 21) (NBT) S 67° E 15½ links



5" Tamarack (S 17) (NBT) N 31° W 12½ links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from 2 old wood posts which check well with corners in vicinity.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 4-3-64
REGISTERED LAND SURVEYOR
Billy D. Buckler