

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 43 N.R. 27 W


Dickinson COUNTY

DESCRIPTION OF CORNER 1/4 Corner for Section 17/16

CORNER MONUMENT 1" Iron pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 11-1-63

WITNESSES TO CORNER..... 10" W. Birch (1/4 S) (NBT) S 83° E 47½ links



8" W. Birch (1/4 S) (NBT) S 21° E 18 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between Section Corners.

Corner lies on south side of old road which may account for no original evidence.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 4-3-64  
REGISTERED LAND SURVEYOR  
Billy D. Buckler