

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION



LAND CORNER RECORD

T. 43 N. R. 27 W


Dickinson COUNTY

DESCRIPTION OF CORNER S 1/16 Corner for Sections 5/4

CORNER MONUMENT 1" Iron Pipe with 1/4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 10-29-63

WITNESSES TO CORNER..... 12" Cedar (S 1/16) (BT) S 19° E 219 links
to 1/2 of old Dam, East, 86 links



CIRCLE CORNER REGISTERED

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on lines between Section Corner to south and 1/4 Corner to North.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 4-3-64
REGISTERED LAND SURVEYOR
Billy D. Buckler